DOCKET NO.: 292783US6PCT/ab

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Giovanni STEFANI

PATENT NO.: 7,674,164 GROUP: 3749

ISSUED: March 9, 2010 EXAMINER: OREILLY, PATRICK F

FOR: AN AIR-CONDITIONING SYSTEM FOR THE PASSENGER COMPARTMENT

OF A VEHICLE

REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a Request for Certificate of Correction in Serial Number 10/583,551, now U.S. Patent Number 7,674,164.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, L.L.P.

Gregory J. Maier

Registration No. 25,599

James H. Knebei Registration No. 22,630

Colin B. Harris

Registration No. 58,969

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/09) UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.: 7,674,164

DATED: **Mar. 9, 2010**

INVENTOR(S): Stefani

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (30), the Foreign Application Priority Data is incorrect. Item (30) should read:

-- (30) Foreign Application Priority Data

Dec. 19, 2003 (IT)BO2003A0765 --

Mailing address of sender:

OBLON, SPIVAK MCCLELLAND, MAIER & NEUSTADT, L.L.P. 1940 DUKE STREET ALEXANDRIA, VIRGINIA 22314 Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/09) Patent No.

7,674,164

No. of add'l copies @ .30 per page

